



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF STATE LANDS AND FORESTRY

Norman H. Bangert
Governor

Dee C. Hansen
Executive Director

Richard J. Mitchell
Division Director

355 West North Temple
3 Triad Center, Suite 400
Salt Lake City, Utah 84180-1204
801-538-5508

RECEIVED

NOV 14 1991

DIVISION OF
OIL GAS & MINING

November 13, 1991

James F. Maxwell
722 E. 2730 No.
Provo, UT 84604

Dear Mr. Maxwell:

RE: ML 41160; DOGM /047/024

I revisited your leasehold on November 13, 1991. I observed that you have cleaned up the site and have implemented measures to control drainage out of the pit area.

You should inspect the berm which you constructed across the lower end of the pit and examine the PVC drainage pipe for leaks at least semiannually. Repair any deterioration which may occur to these improvements.

No additional overburden materials should be dumped over the lower end of the pit. Overburden should rather be stored above the upper end of the pit area. Overburden materials should be compacted in storage and should be stabilized with mulch or seeding at the surface for long term storage.

Your cooperation is appreciated.

Sincerely yours,

JOHN T. BLAKE
MINERAL RESOURCES SPECIALIST

JTB/tdw

cc: Seabrook Corp.
Attn: Marilyn Joyce
555 17th Street
Suite 1000
Denver, CO 80202

Edward W. Bonner, Division of State Lands and Forestry

Wayne Hedberg, Division of Oil, Gas, and Mining